

cartrend



FUSION





ABARTH (FIAT)

Punto [199..]	05.08 →	B1	HB65	HB38
Punto Grande [199..]	12.07 - 12.12	B1	HB65	HB38

ALFA ROMEO

145 [930]	04.97 - 12.00	A	HB55	HB48
146 [930]	04.97 - 12.00	A	HB55	HB48
147 [937]	11.00 - 06.05	A	HB55	HB40
147 [937]	04.05 - 12.10	C	HB55	HB40
156 Berlina [932]	10.97 - 12.05	A	HB55	HB50
156 Sport Wagon [932]	06.00 - 12.05	A	HB55	HB50
159 Berlina [939]	06.05 - 12.11	C	HB58	HB45
159 Sport Wagon [939]	06.05 - 12.11	C	HB58	HB45
166 [936]	07.98 - 10.07	A	HB53	HB48
Brera [939]	01.06 - 12.10	C	HB58	HB45
Giulia [952]	03.16 →	B2	HB60	HB45
Giulietta [940]	04.10 →	B2	HB58	HB45
GT [937]	04.05 - 12.10	C	HB55	HB40
Mito [955]	05.08 - 12.18	B1	HB65	HB38
Spider [939]	03.06 - 12.10	C	HB58	HB45
Stelvio	11.16 →	B2	HB65	HB45

AUDI

A1 [8X1]	05.10 - 10.18	B2	HB60	HB40
A1 Sportback [8XA]	09.11 - 10.18	B2	HB60	HB40
A3 [8V1]	04.12 →	B2	HB65	HB45
A3 Cabriolet [8P7]	04.08 - 05.13	B1	HB60	HB45
A3 Cabriolet [8V7]	10.13 →	B2	HB65	HB45
A3 Limousine [8VS]	05.13 →	B2	HB65	HB45
A3 Sportback [8PA]	09.04 - 03.13	B1	HB60	HB48
A3 Sportback [8VA]	09.12 →	B2	HB65	HB45
A4 [8W2;B9]	05.15 →	B2	HB60	HB50
A4 [8K2;B8]	11.07 - 12.15	B2	HB60	HB50



AUDI

A4 Allroad [8WH]	01.16 →	B2	HB60	HB50
A4 Allroad [8KH]	04.09 – 04.16	B2	HB60	HB50
A4 Avant [8W5;B9]	05.15 →	B2	HB60	HB50
A4 Avant [8K5;B8]	11.07 – 12.15	B2	HB60	HB50
A5 Cabriolet [8F7]	03.09 – 01.17	B2	HB60	HB53
A5 Cabriolet [F57]	09.16 →	B2	HB60	HB53
A5 Coupé [8T3]	06.07 – 10.07	B2	HB60	HB50
A5 Coupé [F53]	06.16 →	B2	HB60	HB55
A5 Coupé [8T3]	11.07 – 01.17	B2	HB60	HB50
A5 Sportback [8TA]	05.09 – 01.17	B2	HB60	HB50
A5 Sportback [F5A]	06.16 →	B2	HB60	HB50
A6 [4A2;C8]	04.18 →	B2	HB60	HB50
A6 [4G2;C7]	11.10 →	B2	HB60	HB53
A6 Avant [4A5;C8]	02.18 →	B2	HB60	HB50
A6 Avant [4G5;C7]	05.11 →	B2	HB65	HB53
A6 Avant Allroad [4GH;C7]	01.12 →	B2	HB65	HB53
A7 Sportback [4GA]	07.10 – 05.18	B2	HB65	HB53
A8 [4H;D4]	11.09 →	B2	HB70	HB50
Q2 [GAB]	06.16 →	B2	HB60	HB48
Q3 [8UB]	06.11 →	B2	HB60	HB53
Q5 [FYB]	05.16 →	B2	HB60	HB50
Q5 [8RB]	11.08 – 08.17	B2	HB60	HB50
Q7 [4LB]	03.06 – 08.15	B1	HB65	HB60
Q7 [4MB]	01.15 →	B2	HB70	HB50
RS Q3 [8UB]	10.13 →	B2	HB60	HB53





AUDI

RS3 Limousine [8VS]	02.17 →	B2	HB65	HB45
RS3 Sportback [8PA]	01.11 – 12.12	B1	HB60	HB48
RS3 Sportback [8VA]	02.15 →	B2	HB65	HB45
RS4 Avant [8K5;B8]	05.12 – 08.15	B2	HB60	HB50
RS4 Avant [8W5;B9]	09.17 →	B2	HB60	HB50
RS5 Cabriolet [8F7]	11.12 – 08.15	B2	HB60	HB53
RS5 Coupé [8T3]	03.10 – 08.15	B2	HB60	HB50
RS5 Coupé [F53]	03.17 →	B2	HB60	HB50
RS5 Sportback [F5A]	06.18 →	B2	HB60	HB50
RS6 Avant [4GH;C7]	01.13 →	B2	HB65	HB53
RS7 Sportback [4GA]	05.13 – 04.18	B2	HB65	HB53
S1 [8X]	01.14 →	B2	HB60	HB38
S1 Sportback [8X]	01.14 →	B2	HB60	HB38
S3 [8P1]	11.06 – 03.13	B1	HB60	HB48
S3 [8V1]	11.12 →	B2	HB65	HB45
S3 Cabriolet [8V7]	05.14 →	B2	HB65	HB45
S3 Limousine [8VS]	10.13 →	B2	HB65	HB45
S3 Sportback [8VA]	05.13 →	B2	HB65	HB45
S3 Sportback [8PA]	07.08 – 03.13	B1	HB60	HB48
S4 [8K2;B8]	03.09 – 12.15	B2	HB60	HB50
S4 [8W2;B9]	05.16 →	B2	HB60	HB50
S4 Avant [8K5;B8]	03.09 – 12.15	B2	HB60	HB50
S4 Avant [8W5;B9]	05.16 →	B2	HB60	HB50
S5 Cabriolet [8F7]	05.09 →	B2	HB60	HB53
S5 Cabriolet [F57]	11.16 →	B2	HB60	HB53
S5 Coupé [F53]	07.16 →	B2	HB60	HB50
S5 Coupé [8T3]	11.07 – 01.17	B2	HB60	HB50
S5 Sportback [8TA]	01.10 – 01.17	B2	HB60	HB50
S5 Sportback [F5A]	07.16 →	B2	HB60	HB50
S6 [4G2;C7]	04.12 →	B2	HB65	HB53
S6 Avant [4GH;C7]	04.12 →	B2	HB65	HB53
S7 Sportback [4GA]	04.12 →	B2	HB60	HB53
S8 [4H;D4]	04.12 →	B2	HB70	HB50
SQ5 [FYB]	11.16 →	B2	HB60	HB50
SQ5 [8RB]	12.12 →	B2	HB60	HB50
SQ7 [4MB]	04.16 →	B2	HB70	HB50




AUDI

TT Coupé [8N3]	05.03 – 06.06	C	HB53	HB53
TT Coupé [8J3]	07.06 – 08.15	B1	HB55	HB53
TT Coupé [FV3]	07.14 →	B2	HB60	HB53
TT Roadster [8J9]	02.07 – 06.14	B1	HB55	HB53
TT Roadster [8N9]	05.03 – 06.06	C	HB53	HB53
TT Roadster [FV3]	11.14 →	B2	HB60	HB53
TT RS Coupé [FV3]	05.16 →	B2	HB60	HB53
TT RS Coupé [8J3]	07.09 – 06.14	B1	HB55	HB53
TT RS Roadster [FV9]	05.16 →	B2	HB60	HB53
TT RS Roadster [8J9]	07.09 – 06.14	B1	HB55	HB53
TTS Coupé [8J3]	05.08 – 08.15	B1	HB55	HB53
TTS Coupé [FV3]	11.14 →	B2	HB60	HB53
TTS Roadster [FV]	02.15 →	B2	HB60	HB53
TTS Roadster [8J9]	05.08 – 06.14	B1	HB55	HB53

BMW

M3 [F80]	06.14 →	B1	HB60	HB48
M4 [F82]	06.14 →	B1	HB60	HB45
Serie 1 [E81;E87]	09.04 – 12.11	B1	HB50	HB50
Serie 1 [F20;F21]	09.11 →	B1	HB55	HB45
Serie 1 Cabrio [E88]	03.08 – 10.13	B1	HB50	HB50
Serie 1 Coupé [E82]	10.07 – 10.13	B1	HB50	HB50
Serie 2 ActiveTourer [F45]	09.14 →	B2	HB65	HB48
Serie 2 Cabrio [F23]	09.14 →	B1	HB55	HB45
Serie 2 Coupé [F22]	09.13 →	B1	HB55	HB45
Serie 2 Gran Tourer [F46]	06.15 →	B2	HB65	HB48
Serie 3 [F30]	02.12 →	B1	HB60	HB48





BMW

Serie 3 [E90]	03.05 – 08.09	C	HB60	HB48
Serie 3 [E90]	09.09 – 08.13	B1	HB60	HB48
Serie 3 Cabrio [E93]	09.09 – 10.13	B1	HB60	HB40
Serie 3 Coupé [E92]	09.09 – 08.13	B1	HB60	HB40
Serie 3 GT [F34]	06.13 →	B1	HB60	HB48
Serie 3 Touring [E91]	09.05 – 08.09	C	HB60	HB48
Serie 3 Touring [E91]	09.09 – 05.13	B1	HB60	HB48
Serie 3 Touring [F31]	09.12 →	B1	HB60	HB48
Serie 4 Cabrio [F33]	03.14 →	B1	HB60	HB45
Serie 4 Coupé [F32]	09.13 →	B1	HB60	HB45
Serie 4 GC [F36]	05.14 →	B1	HB60	HB45
Serie 5 [E60]	07.03 – 02.10	B1	HB60	HB58
Serie 5 [F10]	03.10 – 10.16	C	HB65	HB45
Serie 5 [G30]	02.17 →	B2	HB65	HB48
Serie 5 GT [F07]	09.09 →	C	HB65	HB45
Serie 5 Touring [E61]	05.04 – 08.10	B1	HB60	HB58
Serie 5 Touring [F11]	09.10 →	C	HB65	HB45
Serie 5 Touring [G31]	06.17 →	B2	HB65	HB48
Serie 6 [E63]	01.04 – 07.10	B1	HB60	HB58
Serie 6 [F13]	10.11 →	C	HB65	HB40
Serie 6 Cabrio [E64]	04.04 – 07.10	B1	HB60	HB58
Serie 6 Cabrio [F12]	03.11 →	C	HB65	HB40
Serie 6 GC [F06]	05.12 →	C	HB65	HB40
Serie 6 Gran Turismo [G32]	10.17 →	B2	HB65	HB45
Serie 7 [F01;F02;F04]	11.08 →	C	HB65	HB45
Serie 7 [G11; G12]	09.15 →	B2	HB65	HB48
Serie M [E60;E63]	11.04 →	B1	HB60	HB55
Serie M Cabrio [E64]	11.06 – 02.08	B1	HB60	HB55
X1 [E84]	10.09 – 06.15	B1	HB60	HB48
X1 [F48]	10.15 →	B2	HB65	HB40
X3 [F25]	10.10 – 08.17	C	HB65	HB50
X4 [F26]	06.14 →	C	HB65	HB50
X5 [E70]	11.06 – 09.11	C	HB60	HB50
X5 [E70]	10.11 – 06.13	B2	HB60	HB50
X6 [E71;E72]	03.08 – 09.11	C	HB60	HB50
X6 [E71]	10.11 – 06.14	B2	HB60	HB50




CADILLAC

ATS	09.12 →	A	HB55	HB48
CTS	09.02 – 08.07	A	HB55	HB53
CTS	09.07 – 08.10	A	HB55	HB48
Escalade	09.06 – 08.08	B1	HB55	HB55
Escalade	09.09 – 08.13	A	HB55	HB53
SRX	09.03 – 08.09	A	HB55	HB53
SRX	09.09 →	B2	HB65	HB40

CHEVROLET

Aveo [KL1S,T250/T255]	02.06 – 12.11	A	HB55	HB40
Aveo [KL1T,T300]	06.11 – 12.17	B1	HB65	HB38
Aveo Hatchback [KL1S,T250/T255]	02.06 – 12.11	A	HB55	HB40
Aveo Hatchback [KL1T,T300]	06.11 – 12.17	B1	HB65	HB38
Captiva [KL1C,C100]	10.06 – 02.11	A	HB60	HB40
Captiva [KL1C,C140]	04.11 →	A	HB60	HB40
Cruze [KL1J,J300]	05.09 →	A	HB60	HB45
Epica [V250]	06.06 – 12.11	A	HB55	HB50
Evanda [KL1L,V200]	02.03 – 09.06	A	HB55	HB50
HHR	02.08 – 05.09	A	HB45	HB45
Kalos Hatchback [KL1S,T200]	02.05 – 04.08	A	HB55	HB40
Lacetti [KL1N,J200]	02.05 – 04.13	A	HB55	HB48
Lanos	01.04 →	A	HB48	HB48
Nubira [KL1N,J200]	02.05 – 04.13	A	HB55	HB48
Nubira Station Wagon [KL1N,J200]	02.05 – 04.13	A	HB55	HB48
Orlando	10.10 →	A	HB60	HB48
Spark [M300]	12.09 →	A	HB58	HB38
Volt [1G1]	11.11 – 12.14	B2	HB65	HB65





CHRYSLER

300 [LX]	09.04 – 08.10	A	HB55	HB55
300C [LE]	10.04 – 08.10	A	HB55	HB55
300C Touring [LE]	10.04 – 08.10	A	HB55	HB55
300M [LH]	09.98 – 12.04	A	HB60	HB48
Crossfire [ZH]	09.03 – 08.08	A	HB55	HB50
Grand Voyager [RS]	09.07 – 11.09	A	HB65	HB50
Grand Voyager [RS]	12.09 →	A	HB65	HB50
Neon [PL]	06.99 – 12.05	A	HB55	HB48
PT Cruiser [PT]	06.00 – 12.10	A	HB53	HB50
PT Cruiser Cabrio [PT]	09.00 – 12.10	A	HB53	HB50
Sebring [JR]	09.00 – 08.06	A	HB55	HB53
Sebring [JS]	09.06 →	A	HB60	HB55
Sebring Cabrio [JR]	01.01 – 09.09	A	HB55	HB53
Sebring Cabrio [JS]	09.06 →	A	HB60	HB55
Voyager [RT]	01.08 – 11.09	A	HB65	HB50
Voyager [RT]	12.09 →	A	HB65	HB50

CITROËN

Berlingo [B9]	05.08 →	B2	HB65	HB40
Berlingo [K9]	07.18 →	B2	HB65	HB40
Berlingo [M49]	07.96 – 11.02	A	HB55	HB53
C1 I [B0]	06.05 – 12.14	A	HB65	-
C1 II [B4]	02.14 →	B1	HB65	-
C3 Aircross [A88]	06.17 →	B2	HB65	HB40
C3 I [A8, A31]	01.02 – 12.09	A	HB60	HB45
C3 III [B618]	07.16 →	B2	HB65	HB40
C3 Picasso [A58]	02.09 – 03.10	B2	HB60	HB40
C3 Pluriel [A42]	05.03 – 10.12	A	HB53	HB45
C4 Coupé [B5]	11.04 – 07.10	B1	HB70	HB60
C4 I [B5]	11.04 – 09.10	B1	HB70	HB60
C5 [X4]	03.01 – 11.03	A	HB65	HB45
C5 [X4]	12.03 – 09.04	C	HB65	HB48
C5 [X3]	10.04 – 03.08	C	HB65	HB48
C5 [X7]	04.08 – 12.18	B1	HB70	HB55
C5 Break [X4]	06.01 – 11.03	A	HB65	HB45
C5 Break [X4]	12.03 – 09.04	C	HB65	HB48
C5 Break [X3]	10.04 – 03.08	C	HB65	HB48
C5 Tourer [X7]	04.08 – 12.17	B1	HB70	HB55
C6 [X6]	11.05 – 12.12	C	HB70	HB70
C8 [V3]	08.05 – 07.14	A	HB65	HB65
C-Crosser [I4]	09.07 – 01.13	A	HB60	HB53



CITROËN


Jumper [U9]	06.06 →	B2	HB65	HB55
Jumpy [U64]	10.95 – 01.07	A	HB65	HB50
Jumpy [G9]	02.07 – 01.17	A	HB70	HB50
Saxo [S8]	10.99 – 09.03	A	HB50	HB45
Xsara [N6,N7]	07.97 – 12.05	A	HB55	HB50
Xsara Coupé [N6,N7]	07.97 – 12.05	A	HB55	HB50
Xsara Break [N6,N7]	10.97 – 03.10	A	HB55	HB50
Xsara Picasso [N68]	01.00 – 09.05	A	HB65	HB65
Xsara Picasso [N68]	10.05 – 04.10	C	HB65	HB65

DACIA

Dokker [FE/KE]	07.12 – 05.15	A	HB55	HB40
Duster [HS]	10.09 – 05.12	A	HB50	HB50
Duster [HS]	06.12 – 11.14	A	HB50	HB50
Duster [HS]	10.14 – 11.16	A	HB60	HB45
Lodgy	03.12 – 04.15	A	HB55	HB40
Logan I [LS]	07.04 – 12.15	A	HB50	HB50
Logan II [L8]	08.12 – 02.15	A	HB55	HB50
Logan MCV I [KS/FS]	01.07 – 12.15	A	HB50	HB50
Logan MCV II [K8]	03.13 – 02.15	A	HB55	HB50
Logan Pick-Up [US]	01.07 – 12.15	A	HB50	HB50
Sandero I [BS]	06.08 – 12.15	A	HB50	HB50
Sandero II [B8]	08.12 – 02.15	A	HB55	HB50

DAEWOO

Evanda	03.03 – 01.05	A	HB55	HB50
Kalos [KLAS]	09.02 – 01.05	A	HB55	HB40
Kalos Hatchback [KLAS]	09.02 – 01.05	A	HB55	HB40
Lacetti [KLAN]	03.04 – 01.05	A	HB55	HB48
Lanos [KLAT]	11.96 – 09.03	A	HB48	HB48
Leganza [KLAV,V100]	03.97 – 12.02	A	HB55	HB50





DAEWOO

Matiz [KLYA, M100]	04.98 - 01.05	A	HB53	HB38
Matiz Creative	09.09 - 08.15	A	HB58	HB38
Nubira [KLAN,J200]	10.99 - 01.05	A	HB55	HB48
Rezzo [KLAU]	09.00 - 01.05	A	HB60	HB45

DAIHATSU

Cuore [L7]	10.98 - 03.03	A	HB45	HB38
Cuore [L2]	03.03 →	A	HB53	-
Gran Move [G3]	11.96 - 07.02	A	HB53	HB48
Materia	09.06 →	A	HB50	HB48
Move	08.95 - 09.02	A	HB40	HB38
Sirion I [M1]	04.98 - 07.04	A	HB48	HB40
Sirion II [M3]	10.04 →	A	HB50	HB40
Terios [J1]	03.97 - 12.05	A	HB50	HB38
Terios [J2]	01.06 →	A	HB53	HB45
Trevis [L6]	08.06 →	A	HB50	HB40

DODGE

Avenger [JS]	09.07 - 08.11	A	HB60	HB55
Caliber [P3]	01.06 - 08.09	A	HB60	HB40
Caliber [PM]	09.06 →	A	HB60	HB40
Journey [JC]	09.06 →	A	HB60	HB45
Nitro [KA]	09.06 - 08.11	A	HB48	HB48

DS (CITROEN) A

DS7	09.17 →	B2	HB70	HB40
-----	---------	----	------	------

FIAT

124 Spider [348]	03.16 →	A	HB45	HB48
500L [199..,CFA]	09.12 →	B2	HB65	HB38
Barchetta [183..]	01.95 - 02.05	A	HB48	HB48
Bravo [198]	03.07 - 12.14	B2	HB60	HB45
Croma [194..]	06.05 - 12.10	C	HB60	HB40
Doblo [263..]	02.10 →	B2	HB60	HB40
Doblo Cargo [263..]	02.10 →	B2	HB60	HB40
Ducato [250;251;290]	06.06 →	B2	HB65	HB55
Freemont [JC]	06.11 - 12.15	A	HB60	HB48
Fullback	05.16 →	A	HB55	HB45
Grande Punto [199..]	10.05 - 12.11	B1	HB65	HB38
Idea [350]	01.04 - 12.05	A	HB58	HB40
Idea [350]	01.06 - 03.08	A	HB58	HB38




FIAT

Idea [350]	04.08 – 12.12	B2	HB58	HB38
Marengo [285..]	01.97 – 09.02	A	HB55	HB48
Multipla [186..]	01.99 – 12.05	A	HB60	HB53
Multipla [186..]	01.06 – 12.10	B1	HB60	HB55
Panda [141..]	01.93 – 09.03	A	HB40	-
Panda [169..]	10.03 – 12.12	A	HB58	HB40
Panda [312..]	02.12 →	B2	HB60	HB38
Punto [199..]	01.12 →	B1	HB65	HB38
Punto Evo [199..]	10.09 – 12.12	B1	HB65	HB38
Scudo [222..]	10.95 – 01.07	A	HB65	HB50
Scudo [272..]	01.07 – 04.16	A	HB65	HB50
Seicento [187..]	03.98 – 12.10	A	HB48	HB48
Siena [178..]	04.97 – 12.01	A	HB58	HB45
Stilo [192..]	10.01 – 06.05	A	HB53	HB48
Stilo [192..]	07.05 – 12.07	B1	HB55	HB48
Stilo Multi Wagon [192..]	07.05 – 12.07	B1	HB55	HB48
Strada [278]	03.99 – 12.11	A	HB58	HB45
Talento '16 [296]	06.16 →	B2	HB65	HB48
Tipo [356]	11.15 →	B2	HB65	HB40
Tipo Hatchback [357]	11.15 →	B2	HB65	HB40
Ulysse [179..]	11.05 – 12.10	A	HB65	HB65

FORD

C-MAX I [07]	03.07 – 07.10	C	HB65	HB48
Ecosport [14]	10.16 →	B2	HB55	HB40
Edge	01.16 →	B1	HB70	-
Fiesta VI [02]	11.01 – 09.08	A	HB55	HB40
Fiesta VII [08]	07.08 – 11.12	B2	HB65	-
Fiesta VII [13]	11.12 →	B2	HB65	HB40
Focus I [99]	08.98 – 05.05	A	HB55	HB48
Focus II [04]	07.04 – 01.06	C	HB65	HB40
Focus II [04;08]	02.06 – 12.11	C	HB65	-
Focus IV [18]	05.18 →	B2	HB65	HB50
Galaxy [00]	04.01 – 08.06	C	HB70	HB70
KA+	07.16 →	B2	HB55	HB40





FORD

Ka I [97]	09.96 - 09.08	A	HB48	HB40
Kuga I [CBV]	02.08 - 11.12	B2	HB60	HB40
Kuga II [DM2]	11.12 →	B1	HB70	HB70
Maverick [1EZ,1N2]	10.00 - 01.07	A	HB48	HB48
Mondeo III [01]	10.00 - 03.07	A	HB55	HB50
Mondeo III Turnier [01]	10.00 - 03.07	A	HB55	HB50
Mondeo IV [07]	02.07 - 12.14	B2	HB65	HB48
Mondeo IV Turnier [07]	02.07 - 12.14	B2	HB65	HB48
Mondeo V [15]	09.14 →	B1	HB65	HB65
Mustang	09.04 - 02.09	A	HB55	HB50
Mustang	03.09 →	B1	HB55	HB50
Mustang-15	04.15 →	B1	HB55	HB50
Ranger	06.94 - 06.09	A	HB45	HB45
Ranger [TKE]	09.11 - 08.15	B2	HB60	HB40
Ranger [TKE]	09.15 →	A	HB60	HB38
Streetka	12.02 - 12.05	A	HB48	HB48
Tourneo Connect [02]	05.02 - 12.13	A	HB55	HB50
Tourneo Courier	04.14 →	B1	HB70	HB38
Transit [00]	01.00 - 07.06	A	HB70	HB58
Transit [06,12]	04.06 - 12.13	A	HB65	HB55
Transit Connect [02]	05.02 - 12.13	A	HB55	HB50
Transit Courier	04.14 →	B1	HB70	HB38
Transit Tourneo [00]	08.00 - 07.06	A	HB70	HB58
Transit Tourneo [06,12]	04.06 - 09.11	A	HB65	HB55

HONDA

Accord [CL/CN/CM]	02.03 - 06.08	A	HB65	HB40
Accord [CU/CW]	07.08 - 12.15	A	HB60	HB55
Accord Hatchback [CG/CH/CL]	12.99 - 02.03	A	HB55	HB48
Accord Sedan [CG/CH/CL]	10.98 - 02.03	A	HB55	HB48
Accord Coupé [CG]	12.97 - 12.02	A	HB60	HB48
Accord Tourer [CL/CN/CM]	02.03 - 08.08	A	HB65	HB40
Accord Tourer [CU/CW]	09.08 - 12.15	A	HB60	HB53
Civic Hatchback [EU/EP]	02.01 - 12.05	A	HB60	HB38
Civic Hatchback [FK]	09.11 - 02.17	A	HB65	HB45
Civic Hatchback [FC/FK]	03.17 →	A	HB65	HB45
Civic Hybrid [FD]	01.08 - 12.10	A	HB65	HB58
Civic Sedan [ES]	02.01 - 01.06	A	HB53	HB45
Civic Sedan [FD]	09.06 - 12.11	A	HB65	HB58
Civic Sedan [FC]	03.17 →	A	HB65	HB45
Civic Tourer [FK]	12.13 →	A	HB65	HB45
CR-V [KL]	07.03 →	A	HB53	HB48
CR-V [RE]	01.07 - 11.12	A	HB65	HB40
CR-V [RE]	10.12 →	A	HB65	HB40
CR-V [RW]	09.18 →	A	HB65	HB40
CR-Z [ZF]	03.10 - 02.14	A	HB65	HB50



HONDA


Crosstour	09.09 – 08.12	A	HB65	HB48
FR-V [BE]	01.05 – 06.09	A	HB65	HB45
HR-V [GH]	12.98 – 02.06	A	HB50	HB40
HR-V [RU]	08.15 →	A	HB65	HB45
Insight Coupé [ZE]	01.00 – 12.06	A	HB50	HB45
Insight Hatchback [ZE]	03.09 – 02.14	A	HB65	HB40
Jazz [GD]	03.02 – 12.08	A	HB53	HB38
S2000	04.99 – 06.09	A	HB50	HB40

HUMMER

H2	09.02 →	A	HB40	HB40
H3	09.06 →	A	HB40	HB40

HYUNDAI

Accent [LC]	05.99 – 06.06	A	HB50	HB45
Accent [MC]	04.06 – 02.12	A	HB55	HB40
Accent [RB]	11.10 →	A	HB65	HB40
Accent Blue [RB]	01.11 →	A	HB65	HB40
Accent Hatchback [LC]	08.99 – 06.06	A	HB50	HB45
Accent Hatchback [MC]	04.06 – 02.12	A	HB55	HB40
Atos [MX]	09.97 – 12.03	A	HB50	HB40
Atos Prime [MX]	09.99 – 03.08	A	HB50	HB40
Elantra [XD]	06.00 – 09.06	A	HB50	HB45
Elantra [HD]	09.05 →	A	HB50	HB45
Elantra [AD]	03.16 →	A	HB65	HB40
Genesis Coupe [BK]	11.08 – 03.16	A	HB60	HB50
Genesis Sedan [BH]	05.11 – 03.16	A	HB60	HB48
Genesis Sedan [DH]	01.14 →	A	HB65	HB40
Grandeur [TG]	07.05 →	A	HB60	HB50
H100	05.05 →	A	HB45	HB45
H350	04.14 →	A	HB65	HB60
H-1	10.97 – 12.07	A	HB65	HB50
H-1	03.08 →	A	HB60	HB50
i10 [PA]	10.07 →	A	HB55	HB40
i10 [IA]	09.13 →	A	HB55	HB40
i20 [PB]	12.08 →	A	HB60	HB40
i20 [GB]	11.14 →	A	HB60	HB40





HYUNDAI

i30 [FD]	09.07 – 03.10	B2	HB60	HB45
i30 [FD]	04.10 – 01.13	A	HB60	HB45
i30 CW [FD]	02.08 – 03.10	B2	HB60	HB45
i30 CW [FD]	04.10 – 09.12	A	HB60	HB45
i30 CW [PD]	03.17 →	A	HB65	HB40
i30 Fastback [PD]	11.17 →	A	HB65	HB40
i40 [VF]	04.11 →	A	HB65	HB40
i40 CW [VF]	04.11 →	A	HB65	HB40
ix35 [LM/EL]	01.10 →	A	HB60	HB40
ix55 [EN]	09.08 – 12.12	B2	HB60	HB50
Ioniq [AE]	03.16 →	A	HB65	HB45
Kona [OS]	06.17 →	A	HB65	HB40
Matrix [FC]	07.01 – 04.10	A	HB55	HB40
Porter507	09.00 – 12.03	A	HB45	HB45
Santa Fe [CM]	03.06 – 12.12	A	HB60	HB45
Santa Fe [TM]	02.18 →	A	HB65	HB40
Sonata III [EF]	03.98 – 03.01	A	HB50	HB50
Sonata IV [EF]	04.01 – 01.05	A	HB55	HB50
Sonata V [NF]	08.04 – 12.10	A	HB60	HB50
Sonata [YF]	09.09 →	A	HB65	HB45
Terracan [HP]	01.01 – 10.06	A	HB55	HB50
Trajjet [FO]	01.00 – 06.07	A	HB65	HB55
Tucson [JM]	08.04 – 03.10	A	HB60	HB40
Tucson [TL]	06.15 →	A	HB65	HB40
Veloster	06.11 →	A	HB65	HB45
XG [F]	12.98 – 12.05	A	HB55	HB50

INFINITI

EX [J50]	04.08 – 06.14	A	HB60	HB45
FX [S50]	11.02 – 08.08	A	HB55	HB50
FX [S51]	07.08 – 12.14	A	HB60	HB48
Q30	11.15 →	B1	HB60	HB48
Q50 [V37]	07.13 →	A	HB65	HB40
Q60 Coupe	08.16 →	A	HB65	HB40
Q70 [Y51]	10.13 →	A	HB65	HB45
QX30	09.16 →	B1	HB60	HB48
QX70 [S51]	11.13 →	A	HB60	HB48

ISUZU

D-Max	05.02 →	A	HB55	HB48
-------	---------	---	------	------

IVECO

Massif	06.08 – 12.12	A	HB45	HB40
--------	---------------	---	------	------

JAGUAR

F-Pace	04.16 →	B2	HB65	HB48
F-Type	10.12 →	A	HB53	HB53



JAGUAR

S-Type [CCX]	10.01 – 03.08	A	HB60	HB45
S-Type [CCX]	10.98 – 04.02	A	HB55	HB55
XE	06.15 →	B2	HB70	HB40
XF [X250]	03.08 – 10.15	B1	HB60	HB48
XF [X260]	10.15 →	B2	HB70	HB40
XF Sportbrake	09.12 – 06.17	B1	HB60	HB48
XF Sportbrake [X260]	07.17 →	B2	HB70	HB40
XJ [X351]	11.09 →	B1	HB60	HB45
XK 8 Cabrio [QDV]	03.96 – 02.09	A	HB53	HB53
XKR 8 Cabrio [QDV]	03.96 – 02.09	A	HB53	HB53
X-Type [CF1]	03.01 – 06.10	A	HB55	HB48
X-Type Estate [CF1]	03.03 – 12.09	A	HB55	HB48

JEEP

Cherokee [KJ]	03.01 – 12.07	A	HB48	HB48
Cherokee [KK]	01.08 – 12.13	A	HB48	HB48
Cherokee [KL]	01.14 →	A	HB65	HB45
Commander [XH]	01.06 – 08.11	A	HB45	HB45
Compass [MK,PK]	10.06 →	A	HB55	HB50
Compass [MX]	06.17 →	A	HB60	HB45
Grand Cherokee [WG]	09.00 – 12.04	A	HB53	HB53
Grand Cherokee [WK]	09.03 →	A	HB53	HB53
Grand Cherokee [WH]	03.05 – 10.11	A	HB53	HB53
Grand Cherokee [WK2]	09.10 – 08.13	A	HB55	HB53
Liberty [KK]	09.07 – 08.13	A	HB48	HB48
Patriot [MK]	10.06 – 08.18	A	HB53	HB53
Renegade	07.14 →	B2	HB55	HB50
Wrangler [TJ]	01.97 – 12.06	A	HB38	HB38
Wrangler [JK]	01.07 →	A	HB38	HB38

KIA

Carens [FC]	04.99 – 08.06	A	HB60	HB45
Carens [FG]	09.06 – 12.12	A	HB65	HB40
Carnival [UP]	06.98 – 06.06	A	HB60	HB60
Carnival [MB]	04.06 →	A	HB65	HB45
Cee'd [ED/FF2]	11.06 – 06.09	B2	HB60	HB45
Cee'd [ED/FF2]	07.09 – 12.12	A	HB60	HB45
Cee'd [CD]	07.18 →	A	HB65	HB40
Cee'd Sporty Wagon [ED/FF2]	09.07 – 06.09	B2	HB60	HB45
Cee'd Sporty Wagon [ED/FF2]	07.09 – 12.12	A	HB60	HB45





KIA

Cerato [FE]	03.04 – 11.09	A	HB60	HB40
Cerato [TD]	12.08 →	A	HB60	HB50
Clarus [GC]	05.96 – 11.01	A	HB53	HB48
Joice [MT]	09.01 – 03.03	A	HB55	HB45
Magentis [GD]	09.00 – 12.05	A	HB55	HB50
Magentis [GE]	02.06 – 04.10	A	HB60	HB45
Niro [DE]	10.16 →	A	HB65	HB40
Opirus [LD]	03.03 – 07.09	A	HB60	HB45
Optima [TF]	09.11 →	A	HB60	HB45
Optima Sports Wagon [JF]	07.16 →	A	HB65	HB45
Picanto [SA]	05.04 – 01.11	A	HB55	HB40
Picanto [TA]	05.11 →	A	HB55	HB40
Pregio [TB]	02.97 – 04.04	A	HB53	HB45
Pregio [TB]	05.04 – 12.12	A	HB53	HB48
Pro Cee'd [ED/FF2]	10.07 – 06.09	B2	HB60	HB45
Pro Cee'd [ED/FF2]	07.09 – 12.12	A	HB60	HB45
Rio [DC]	07.00 – 02.05	A	HB53	HB45
Rio [DE]	03.05 →	A	HB55	HB40
Rio [UB]	06.11 →	A	HB65	HB40
Rio Hatchback [YB]	02.17 →	A	HB65	HB40
Rio Kombi [DC]	09.02 – 02.05	A	HB53	HB45
Sedona	06.98 – 09.05	A	HB60	HB60
Sorento [JC]	07.02 – 08.09	A	HB60	HB45
Sorento [XM]	09.09 →	A	HB60	HB50
Sorento [UM]	02.15 →	A	HB65	HB40
Soul [AM; PS]	02.09 →	A	HB60	HB50
Sportage [JA]	05.93 – 08.04	A	HB50	HB50
Sportage [JE]	09.04 – 05.10	A	HB60	HB40
Sportage [SL]	07.10 →	A	HB60	HB45
Sportage [QL]	01.16 →	A	HB65	HB40
Stinger [CK]	05.17 →	A	HB65	HB45
Stonic [YB]	09.17 →	A	HB65	HB40

LANCIA

Delta [844]	07.08 – 12.14	B2	HB60	HB45
Flavia	03.12 – 12.13	A	HB60	HB55
Lybra Berlina [839]	10.99 – 11.06	A	HB55	HB53
Lybra Station Wagon [839]	10.99 – 11.06	A	HB55	HB53
Musa [184]	10.04 – 01.06	A	HB58	HB40
Musa [184]	02.06 – 09.07	A	HB58	HB38
Musa [184]	10.07 – 12.12	B2	HB58	HB38
Phedra [180]	10.05 – 12.10	A	HB65	HB65
Thema	11.11 – 12.14	A	HB60	-
Thesis [841]	04.02 – 12.09	A	HB65	HB50
Voyager [RT]	09.11 – 12.16	A	HB65	HB50
Y [840]	01.96 – 06.03	A	HB58	HB40
Ypsilon [843]	06.03 – 11.11	A	HB60	HB40
Ypsilon [312,846]	06.11 →	B2	HB60	HB38



LANDROVER

Discovery III	09.04 - 08.09	A	HB55	HB53
Discovery IV	09.09 - 12.17	A	HB55	HB53
Discovery Sport [B5]	09.14 →	A	HB65	HB50
Freelander I [LN]	09.97 - 10.06	A	HB55	HB53
Freelander II [LF]	10.06 - 11.14	B1	HB60	HB50
Range Rover II	09.94 - 08.02	A	HB55	HB55
Range Rover IV [LG]	02.13 - 12.16	A	HB60	HB50
Range Rover Sport I [LS]	03.05 - 08.13	A	HB55	HB53
Range Rover Sport II [LW,L494]	09.13 - 08.16	A	HB60	HB50
Range Rover Velar [L560]	08.17 →	B2	HB65	HB48
Range Rover Evoque [LV,L538]	09.11 →	B2	HB60	HB53

LEXUS

CT200h	12.10 →	A	HB65	HB45
ES [V]	03.06 - 09.12	A	HB60	HB48
ES [V6]	09.12 →	A	HB65	HB45
GS [S1]	08.97 - 01.12	A	HB60	HB50
GS [L1]	01.12 →	A	HB65	HB45
GX 460 [J1]	11.09 →	A	HB65	HB50
GX 470 [J1]	11.02 - 08.09	A	HB55	HB53
IS [E1]	01.99 - 07.05	A	HB55	HB48
IS [E2]	08.05 - 04.13	A	HB55	HB50
IS [E3]	04.13 →	A	HB60	HB45
IS F [E2]	12.07 - 05.14	A	HB55	HB50
LC [Z1]	03.17 →	A	HB65	HB45
LX [J1]	01.98 - 08.07	A	HB50	HB50
LX [J2]	11.07 - 01.12	A	HB60	HB55
LX [J2]	02.12 →	A	HB60	HB55
RC [C1]	09.14 →	A	HB60	HB45
RX [U1]	01.98 - 02.03	A	HB60	HB53
RX [U3]	02.03 - 12.08	A	HB65	HB55
RX [L1]	12.08 - 12.15	A	HB65	HB55
SC Cabrio [Z4]	05.01 - 08.10	A	HB60	HB50

LOTUS

Elisecabrio	09.07 →	A	HB65	-
Europa	07.06 →	A	HB65	-
Evora	05.09 →	C	HB65	-
Exige	04.06 →	A	HB65	-

MASERATI

Ghibli [M157]	01.13 →	B2	HB65	HB45
---------------	---------	----	------	------





MASERATI

Levante	05.16 →	B2	HB65	HB45
Quattroporte [M156]	11.12 →	B2	HB65	HB48

MAZDA

2 [DY]	02.03 – 06.07	A	HB60	HB40
2 [DJ]	10.14 →	A	HB55	HB40
3 [BK]	07.03 – 12.08	C	HB53	HB48
3 [BL]	12.08 – 12.13	A	HB60	HB48
3 [BM;BN]	08.13 →	A	HB60	HB45
5 [CR]	02.05 – 12.10	A	HB65	HB40
5 [CW]	06.10 →	A	HB65	HB40
6 Sedan [GG/GY]	02.02 – 08.07	A	HB55	HB48
6 Sedan [GH]	08.07 – 12.12	A	HB60	HB40
6 Sedan [GL]	09.12 – 09.18	A	HB60	HB45
6 Wagon [GY]	06.02 – 12.07	A	HB55	HB48
6 Wagon [GH]	12.07 – 12.12	A	HB60	HB40
6 Wagon [GL]	10.12 – 09.18	A	HB60	HB45
323 [BJ]	05.98 – 09.03	A	HB53	HB45
626 [GF]	05.97 – 07.02	A	HB53	HB45
626 Fastback [GF]	08.99 – 04.02	A	HB53	HB45
626 Wagon [GW]	10.97 – 04.02	A	HB53	HB45
BT-50 [UN]	03.06 – 07.12	A	HB45	HB45
CX-3 [DK]	02.15 →	A	HB55	HB45
CX-5 [KE]	11.11 →	A	HB60	HB45
CX-7 [ER]	09.06 →	A	HB65	HB40
CX-9 [TB]	09.06 – 12.15	A	HB65	HB40
Demio [DW]	07.96 – 02.03	A	HB50	HB40
MPV [LW]	05.99 – 08.04	A	HB60	HB60
MX-5 [NB]	01.98 – 07.05	A	HB45	HB45
MX-5 [NC]	07.05 – 03.15	A	HB45	HB45
MX-5 [ND]	05.15 →	A	HB45	HB48
Premacy [CP]	03.99 – 05.05	A	HB60	HB40
RX-8 [FE/SE]	04.03 – 04.12	A	HB50	HB45
Serie B [UF/UN]	03.96 – 03.06	A	HB45	HB45
Serie E	02.84 – 12.06	A	HB40	HB40
Tribute [EP]	02.01 – 09.09	A	HB48	HB48
Xedos-9 [TA]	07.93 – 11.02.	A	HB53	HB48

MERCEDES-BENZ

Citan	07.12 →	A	HB55	HB53
Serie A [176]	06.12 – 06.15	B1	HB60	HB48
Serie A [168]	10.97 – 08.04	A	HB65	HB58
Serie A [169]	09.04 – 06.12	B1	HB65	HB58
Serie B [245]	04.05 – 05.11	B1	HB65	HB58
Serie B [246]	09.11 – 06.15	B1	HB65	HB48
Serie C [203]	05.00 – 06.03	A	HB60	HB53
Serie C [204]	01.07 – 11.08	C	HB60	HB60
Serie C [204]	12.08 – 04.13	C	HB60	HB60
Serie C [204]	03.13 – 12.14	B2	HB60	HB60
Serie C [205]	11.13 – 10.14	B1	HB55	HB55
Serie C (T-Modell) [204]	12.08 – 04.13	C	HB60	HB60
Serie C (T-Modell) [204]	03.13 – 12.14	B2	HB60	HB60
Serie C Coupé [204]	03.11 – 04.13	C	HB60	HB60
Serie C (Sportcoupe) [203]	01.01 – 06.03	A	HB60	HB53



MERCEDES-BENZ

Serie CL (Coupé) [215]	03.00 – 08.06	C	HB65	HB65
Serie CL (Coupé) [216]	06.06 →	C	HB65	HB65
Serie CLA [117]	12.12 – 06.15	B1	HB60	HB48
Serie CLA Shooting Brake [117]	01.15 – 06.15	B1	HB60	HB48
Serie CLK (Coupé) [208]	01.97 – 09.02	A	HB60	-
Serie CLK (Cabrio) [208]	09.96 – 01.03	A	HB60	-
Serie CLS [219]	06.04 – 02.11	C	HB65	HB65
Serie CLS Coupé [218]	07.10 – 02.14	C	HB60	HB60
Serie CLS Coupé [218]	03.14 →	B2	HB60	HB60
Serie CLS Shooting Brake [218]	06.12 – 02.14	C	HB60	HB60
Serie CLS Shooting Brake [218]	03.14 →	B2	HB60	HB60
Serie E [210]	06.95 – 08.03	A	HB60	-
Serie E [211]	03.02 – 08.09	C	HB65	HB65
Serie E [212]	08.08 – 02.14	C	HB60	HB60
Serie E [212]	03.14 →	B2	HB60	HB60
Serie E (Cabrio) [207]	01.10 – 04.13	C	HB60	HB60
Serie E (Cabrio) [207]	01.13 →	B2	HB60	HB60
Serie E (Coupé) [207]	02.09 – 04.13	C	HB60	HB60
Serie E (Coupé) [207]	01.13 →	B2	HB60	HB60
Serie GL [164]	02.06 – 12.12	B1	HB70	HB53
Serie GL [166]	08.12 – 09.15	B2	HB65	HB58
Serie GLA [156]	10.13 – 06.15	B1	HB60	HB48
Serie GLE [166]	04.15 →	B2	HB65	HB58
Serie GLE (Coupé) [292]	04.15 →	B2	HB65	HB58
Serie GLK [204]	06.08 – 01.14	C	HB55	HB48
Serie GLK [204]	02.14 →	B2	HB55	HB48
Serie GLS [166]	09.15 →	B1	HB65	HB58
Serie ML [163]	03.98 – 06.05	A	HB55	HB53
Serie ML [164]	03.05 – 08.11	B1	HB70	HB53
Serie ML [166]	06.11 – 08.11	B1	HB70	HB53
Serie ML [166]	09.11 – 04.15.	B2	HB65	HB58
Serie R [251]	09.05 – 10.12	B1	HB70	HB53
Serie S [220]	03.00 – 08.06	C	HB65	HB65
Serie S [221]	09.05 – 12.13	C	HB65	HB65
Serie S [222]	05.13 →	B1	HB65	HB55
Serie SL [230]	10.01 – 11.12	C	HB65	HB65
Serie SLC [172]	12.15 →	B1	HB55	HB55
Serie SLK [170]	09.96 – 03.04	A	HB55	HB53
Serie SLK [171]	04.04 – 02.11	B1	HB55	HB55
Serie SLK [172]	01.11 – 12.15	B1	HB55	HB55
Serie SLR [199]	04.04 – 12.09	C	HB65	HB65
Sprinter [T1N]	02.95 – 05.06	A	HB60	HB53
Sprinter [NCV3]	04.06 →	B1	HB65	HB60
Sprinter Classic [909]	11.13 →	A	HB60	HB53
Vaneo [414]	02.04 – 08.05	B1	HB65	HB58
Viano [639T0N]	09.05 – 08.10	B1	HB70	HB65





MERCEDES-BENZ

Viano [639T0N]	09.10 – 12.14	B1	HB70	HB65
Vito [639T0N]	09.05 – 08.10	B1	HB70	HB65
Vito [639T0N]	09.10 – 12.14	B1	HB70	HB65

MG

TF	03.02 →	A	HB50	HB50
ZR	10.01 – 05.05	A	HB45	HB45
ZS	10.01 – 05.05	A	HB50	HB45
ZT	10.01 – 05.05	A	HB55	HB53
ZT-Tourer	10.01 – 05.05	A	HB55	HB53

MINI (BMW)

Mini [R50,R53]	06.01 – 07.04	A	HB45	HB45
Mini [R50,R53]	08.04 – 11.06	A	HB45	HB45
Mini [R56]	11.06 – 03.12	A	HB45	HB45
Mini [F55,F56]	09.13 →	A	HB45	HB48
Mini Cabrio [R52,R57]	07.04 – 03.12	A	HB45	HB45
Mini Clubman [R55]	11.07 – 03.12	A	HB45	HB45
Mini Clubman [F54]	09.15 →	B2	HB55	HB50
Mini Countryman [R60]	09.10 – 08.16	B1	HB48	HB50
Mini Coupé [R58]	09.11 →	B1	HB50	HB50
Mini Coupé Roadster [R59]	02.12 →	B1	HB50	HB50
Mini Paceman [R61]	03.13 – 09.16	B1	HB48	HB50

MITSUBISHI

ASX [GA]	04.10 →	A	HB60	HB53
Carisma [DA]	05.96 – 12.03	A	HB53	HB50
Carisma Hatchback [DA]	05.95 – 12.03	A	HB53	HB50
Colt [CJ]	11.95 – 06.03	A	HB53	HB48
Colt [CZ]	10.08 – 04.13	A	HB65	-
Colt Cabrio [CZ]	03.06 – 07.08	A	HB65	-
Eclipse Cross [GK]	10.17 →	A	HB60	HB50
Galant [EA]	10.96 – 05.03	A	HB53	HB45
Galant Station Wagon [EA]	10.96 – 09.02	A	HB53	HB45
L 200 [K6/K7]	01.96 – 12.07	A	HB48	HB48
L 200 [KB]	12.05 – 10.09	A	HB53	HB48
L 200 [KA,KB]	11.09 →	A	HB55	HB45
L 200 [KL,KK]	02.15 →	A	HB55	HB45
Lancer [CK/CP/CN]	11.95 – 05.01	A	HB53	HB48
Lancer [CS/CT]	12.00 – 04.10	A	HB60	HB45
Lancer [CY/CZ]	03.07 →	A	HB60	HB40
Lancer Sportback [CX]	07.08 – 08.17	A	HB60	HB40
Lancer Station Wagon [CS/CT]	06.03 – 06.08	A	HB60	HB45
Outlander [CU]	02.03 – 09.07	A	HB55	HB48
Outlander [CW]	02.07 – 12.12	A	HB60	HB53
Outlander [GF]	04.12 →	A	HB65	HB45
Pajero [V60,V70]	02.00 – 08.06	A	HB50	HB50
Pajero [V80,V90]	09.06 →	A	HB55	HB50
Pajero Pinin [H]	10.99 – 02.06	A	HB48	HB48
Pajero Sport [K]	07.96 – 02.09	A	HB50	HB50
Pajero Sport [KH]	07.08 →	A	HB55	HB45
Pajero Sport [KS]	12.15 →	A	HB55	HB45
Space Runner	06.91 – 08.02	A	HB53	HB45
Space Star [DG]	06.98 – 12.04	A	HB53	HB45



NISSAN

350 Z Cabriolet [Z33]	09.03 – 04.09	A	HB50	HB45
350 Z Coupé [Z33]	09.02 – 04.09	A	HB50	HB45
Almera Hatchback [N15]	07.95 – 10.99	A	HB53	HB48
Almera Hatchback [N16E]	01.00 – 09.02	A	HB55	HB40
Almera Hatchback [N16E]	10.02 – 11.06	A	HB55	HB40
Almera [G15RA]	11.12 →	A	HB55	HB40
Almera (Classic) [B10]	01.06 – 11.12	A	HB55	HB40
Almera Sedan [N16;N16E]	04.00 – 11.06	A	HB55	HB40
Almera Tino [V10M]	05.00 – 12.05	A	HB65	HB45
Cabstar [TLO]	10.98 – 08.06	A	HB45	HB45
Cabstar [F24]	09.06 →	A	HB50	HB50
Cube [Z12]	08.09 – 03.11	A	HB50	HB50
Evalia [M20M]	01.11 →	A	HB55	HB40
Kubistar [X76]	07.03 – 03.09	A	HB50	HB50
Leaf [ZE0E]	10.10 →	A	HB65	HB40
Leaf [ZE1E]	01.18 →	A	HB65	HB40
Maxima [A34]	02.03 – 05.08	A	HB65	HB40
Maxima QX [CA33]	01.00 – 01.06	A	HB65	HB45
Micra [K11E]	07.00 – 10.02	A	HB50	HB45
Micra [K12E]	11.02 – 05.05	A	HB53	HB45
Micra [K12E]	06.05 – 10.10	A	HB53	HB45
Micra CC [K12E]	09.05 – 10.10	A	HB53	HB45
Murano [Z50]	09.02 – 12.08	A	HB65	HB45
Murano [Z51]	06.08 →	A	HB65	HB40
Murano [Z52R]	06.16 →	A	HB65	HB45
Navara [D22]	06.00 →	A	HB48	HB48
Navara [D40;D40M;D40T]	05.05 →	A	HB60	HB48
Navara [D23M]	11.15 →	A	HB60	HB40
NP200	10.08 →	A	HB50	HB50
NP300 [D22]	09.08 →	A	HB48	HB48
NV200 [M20;M20M]	08.09 →	A	HB55	HB40
NV300 [X82]	09.16 →	B2	HB65	HB48
NV400 [X62]	09.11 →	A	HB65	HB65
Pathfinder [R50]	10.97 – 10.04	A	HB55	HB50
Pathfinder [R51]	01.05 – 11.14	A	HB60	HB48
Pathfinder [R52R]	09.14 →	A	HB65	HB40
Patrol [260]	04.89 – 12.05	A	HB48	HB48
Patrol [Y62]	03.10 →	A	HB60	HB45
Patrol GR [Y61]	10.97 – 03.10	A	HB50	HB50
Primastar [X83]	07.02 →	A	HB60	HB53
Primera Sedan [P11E]	06.96 – 12.01	A	HB53	HB50
Primera Sedan [P12E]	12.01 – 09.10	A	HB65	HB45
Primera Hatchback [P11E]	06.96 – 12.01	A	HB53	HB50
Primera Hatchback [P12E]	05.02 – 09.10	A	HB65	HB45
Primera Wagon [P11E]	01.98 – 12.00	A	HB53	HB50
Primera Wagon [P11E]	12.00 – 12.01	A	HB53	HB50
Primera Wagon [P12E]	12.01 – 09.10	A	HB65	HB45
Qashqai [J10]	12.06 – 12.13	B1	HB60	HB38
Qashqai [J11E;J11R]	12.13 →	A	HB65	HB40





NISSAN

Qashqai+2 [JJ10]	08.08 – 12.13	B1	HB60	HB38
Terrano I [WD21]	09.95 – 12.06	A	HB53	HB50
Terrano II [R20]	11.99 →	A	HB53	HB50
Terrano [HS]	10.13 – 09.14	A	HB50	HB50
Vanette Cargo [C23M]	07.92 – 11.01	A	HB60	HB60
X-Trail [T30]	10.00 – 08.07	A	HB60	HB40
X-Trail [T31]	04.07 – 12.14	A	HB60	HB40
X-Trail [T32;T32R; T32RR]	04.14 →	A	HB65	HB40

OPEL

Adam	03.13 →	B2	HB65	HB40
Agila [A]	06.00 – 02.08	A	HB50	HB45
Agila [B]	03.08 – 08.15	A	HB55	HB40
Ampere	10.11 – 12.15	B2	HB65	HB65
Antara	05.06 – 12.17	A	HB60	HB40
Astra [G]	09.97 – 12.05	A	HB50	HB48
Astra [H]	03.04 – 08.13	C	HB55	HB45
Astra [J]	09.09 →	B2	HB70	HB60
Astra [K]	09.15 →	B2	HB70	HB60
Astra Coupé [G]	09.97 – 02.05	A	HB50	HB48
Astra GTC [H]	03.05 – 09.09	C	HB55	HB45
Astra GTC [J]	09.11 →	B2	HB70	HB60
Astra Sedan [J]	09.12 →	B2	HB70	HB60
Astra Sports Tourer [J]	09.10 →	B2	HB70	HB60
Astra Sports Tourer [K]	02.16 →	B2	HB70	HB60
Astra TwinTop [H]	09.05 – 10.10	C	HB55	HB45
Calibra	06.90 – 03.97	A	HB48	HB48
Cascada	03.13 →	B2	HB70	HB60
Combo	09.94 – 10.01	A	HB45	HB45
Combo [Tour]	10.01 – 01.12	A	HB50	HB40
Combo [D]	02.12 →	B2	HB60	HB40
Combo [E]	09.18 →	B2	HB65	HB40
Corsa [B]	03.93 – 09.00	A	HB45	HB45
Corsa [C]	09.00 – 09.06	A	HB50	HB45
Corsa [D]	07.06 – 08.15	B1	HB65	HB40
Corsa [E]	10.14 →	B1	HB65	HB40
Crossland X	01.17 →	B2	HB65	HB40
Frontera [A;B]	09.91 – 09.04	A	HB48	HB48
Grandland X	10.17 →	B2	HB70	HB40
GT [B]	06.07 – 12.09	A	HB55	HB40
Insignia [A]	09.08 – 12.17	A	HB60	HB45
Insignia Grand Sport [B]	03.17 →	A	HB60	HB50
Insignia Sports Tourer [A]	02.09 – 12.17	A	HB60	HB45
Insignia Sports Tourer [B]	03.17 →	A	HB60	HB50
Meriva [A]	03.03 – 03.10	A	HB60	HB55
Movano [B]	04.10 →	A	HB65	HB65
Omega [B]	09.93 – 09.03	A	HB60	HB48
Signum	05.03 – 09.08	A	HB60	HB48
Tigra TwinTop [B]	06.04 – 12.09	A	HB50	HB45
Vectra [B]	09.95 – 09.03	A	HB48	HB48
Vectra [C]	09.01 – 10.08	A	HB60	HB48
Vectra Caravan [B]	09.95 – 09.03	A	HB48	HB48
Vectra Caravan [C]	09.03 – 10.08	A	HB60	HB48
Vivaro [A]	03.01 – 08.14	A	HB60	HB53
Vivaro [B]	10.14 →	B2	HB65	HB48
Zafira [A]	03.99 – 07.05	A	HB60	HB55
Zafira [B]	07.05 – 08.15	B1	HB70	HB55



PEUGEOT

106 [S2]	10.99 – 05.05	A	HB50	HB45
107 [B0]	06.05 – 12.14	A	HB65	-
108 [B3]	02.14 →	B1	HB65	-
206 [T1]	06.98 – 02.09	A	HB65	HB40
208	01.12 →	B2	HB65	HB40
306 [N5]	01.99 – 10.03	A	HB55	HB50
307 [T5]	08.00 – 05.05	A	HB70	HB65
307 [T5]	10.04 – 05.05	B1	HB70	HB65
307 CC [T6]	06.05 – 03.09	B1	HB70	HB65
307 CC [T5]	10.03 – 05.05	B1	HB70	HB60
308 II [T9]	07.13 →	B2	HB60	HB45
406 [D9]	04.99 – 06.04	A	HB60	HB55
508	10.10 →	B2	HB65	HB65
806 [U60]	06.94 – 08.02	A	HB65	HB50
807 [V2]	08.05 – 12.13	A	HB65	HB65
1007 [A08]	04.05 – 02.11	A	HB60	HB45
2008	03.13 →	B2	HB65	HB40
4007 [I3]	09.07 – 11.12	A	HB60	HB53
4008	03.12 →	A	HB60	HB53
206 CC [T1]	09.00 – 03.07	A	HB65	HB40
206+ [T3]	03.09 – 05.13	A	HB65	HB40
206 SW [T1]	03.02 – 12.06	A	HB65	HB40
207 [A7]	05.06 – 04.12	C	HB65	HB40
207 CC [A7]	03.07 – 06.15	C	HB65	HB40
207+ [A7]	11.12 – 06.15	C	HB65	HB40
207 SW [A7]	06.07 – 12.13	C	HB65	HB40
306 Break [N5]	05.97 – 03.02	A	HB55	HB50
308 SW II [T9]	01.14 →	B2	HB60	HB45
406 Coupé [D8;D9]	03.97 – 02.05	A	HB65	HB50
406 Break [D8;D9]	10.96 – 06.04	A	HB60	HB55
508 RXH	09.11 →	B2	HB65	HB65
508 SW	10.10 →	B2	HB65	HB65
Boxer [U3]	02.94 – 02.02	A	HB55	HB53
Boxer [U5]	02.02 – 05.06	A	HB55	HB53
Boxer [U9]	06.06 →	B2	HB65	HB55
Expert [U64]	09.95 – 01.07	A	HB65	HB50
Expert [G9]	02.07 – 12.16	A	HB70	HB50
Partner [M4]	07.96 – 08.02	A	HB55	HB53
Partner [M5]	09.02 – 10.11	A	HB55	HB53
Partner [B9]	05.08 – 12.18	B2	HB65	HB40
Partner [K9]	09.18 →	B2	HB65	HB40
Ranch [M4]	07.97 – 08.02	A	HB55	HB53
RCZ [T75]	01.10 →	B2	HB65	HB65
Rifter [K9]	07.18 →	B2	HB65	HB40

PORSCHE

911 [996]	09.97 – 07.04	A	HB55	HB53
911 [996T; GT2,3]	06.00 – 09.05	A	HB55	HB53
911 [991;992]	11.11 →	B2	HB53	HB58
Boxter [986,987]	10.96 – 09.12	A	HB55	HB53
Boxster [981]	04.12 – 08.16	B2	HB53	HB58





PORSCHE

Boxster [718]	03.16 →	B2	HB53	HB58
Cayenne [9PA]	09.02 – 08.10	C	HB65	HB65
Cayenne [92A]	09.10 →	C	HB65	-
Cayenne [9YA]	09.17 →	B2	HB65	HB55
Cayman [987C]	11.05 – 12.12	A	HB55	HB53
Cayman [981C]	03.13 – 08.16	B2	HB53	HB58
Cayman [718C]	09.16 →	B2	HB53	HB58
Macan [95B]	03.14 →	B2	HB60	HB50
Panamera [970]	03.09 – 08.13	A	HB60	HB53
Panamera [970]	09.13 – 10.16	B2	HB65	HB50
Panamera [971]	09.16 →	B2	HB60	HB53
Panamera Sport Turismo [971]	03.17 →	B2	HB60	HB53

RENAULT

19 [X53]	09.88 – 12.01	A	HB50	HB50
Alaskan [U3]	11.17 →	A	HB60	HB40
Clio I [X57]	03.94 – 02.98	A	HB50	HB50
Clio II [BB./CB./SB.]	03.98 – 05.09	A	HB53	HB45
Fluence [L38]	11.09 →	A	HB60	HB40
Kadjar [HL]	06.15 – 04.17	A	HB65	HB40
Kangoo I [FC./KC.]	10.97 – 12.07	A	HB50	HB50
Kangoo II [FW./KW.]	01.08 →	A	HB55	HB53
Koleos [HY.]	09.08 – 09.17	B1	HB60	HB48
Koleos [HC]	09.17 →	A	HB65	HB40
Laguna I [B56; 556]	01.94 – 03.01	A	HB60	HB45
Laguna I Grandtour [A56; K56; S56]	02.95 – 02.01	A	HB60	HB45
Laguna II [BG.]	03.01 – 09.07	A	HB60	HB50
Laguna II Grandtour [KG.]	03.01 – 09.07	A	HB60	HB50
Master I	09.80 – 09.97	A	HB60	HB60
Master III	02.10 →	A	HB65	HB65
Mégane I [X64]	01.96 – 10.02	A	HB55	HB50
Mégane I Cabrio [X64]	09.96 – 09.03	A	HB55	HB50
Mégane I Classic [X64]	09.96 – 09.03	A	HB55	HB50
Mégane I Coupé [X64]	01.96 – 10.02	A	HB55	HB50
Mégane I Grandtour [X64]	07.98 – 10.01	A	HB55	HB50
Mégane I Grandtour [X64]	11.01 – 09.03	A	HB55	HB50
Mégane II [LM]	09.02 – 01.06	A	HB60	HB45
Mégane II Cabrio [EM]	10.03 – 01.06	A	HB60	HB45
Mégane II Grandtour [KM.]	10.03 – 01.06	A	HB60	HB45
Modus [FP./JP.]	06.04 – 05.05	C	HB70	HB65
Modus [FP./JP.]	06.05 – 12.15	C	HB70	HB65
Safrane [B54]	04.92 – 12.00	A	HB60	HB60
Scénic I [JA.]	01.96 – 04.03	A	HB60	HB40
Trafic I	03.89 – 05.01	A	HB50	HB50
Trafic II [EL./FL./JL.]	05.01 – 12.14.	A	HB60	HB53
Trafic II [EL./FL./JL.]	05.14 →	B2	HB65	HB48
Twingo I [C0./S0.]	03.93 – 05.07	A	HB65	-
Twingo II [CN; CN/GN]	04.07 – 12.15	B2	HB60	HB40
Twizy [MA]	03.12 →	A	HB45	-
Wind	04.10 – 12.14	B2	HB60	HB40

ROVER

25	02.00 – 09.04	A	HB45	HB45
25	10.04 – 05.05	A	HB45	HB45
45	02.00 – 05.05	A	HB50	HB45
75	01.99 – 05.05	A	HB55	HB53
75Tourer	01.01 – 05.05	A	HB55	HB53
Serie200	10.89 – 03.00	A	HB45	HB45
Serie600	04.93 – 09.00	A	HB55	HB50
Serie800	10.91 – 09.99	A	HB50	HB50
Streetwise	09.03 – 12.05	A	HB45	HB45



SAAB


9-3 [9400]	03.98 – 09.02	A	HB53	HB50
9-3 [9440]	09.07 – 06.12	B1	HB60	HB58
9-3 Cabriolet [9400]	03.98 – 08.03	A	HB53	HB50
9-3 Cabriolet [9440]	09.07 – 06.12	B1	HB60	HB58
9-3 Coupé [9400]	03.98 – 08.03	A	HB53	HB50
9-3 Kombi [9440]	09.07 – 06.12	B1	HB60	HB58
9-3 X [9440]	03.10 – 06.12	B1	HB60	HB58
9-5 II [650]	03.10 – 06.12	A	HB60	HB53

SEAT

Alhambra [710, 711]	07.10 →	B2	HB70	HB40
Arona [KJ7]	07.17 →	B2	HB65	HB45
Arosa [6H1]	03.99 – 06.04	A	HB53	HB48
Ateca [KH7]	04.16 →	B2	HB65	HB45
Cordoba [6K2]	09.93 – 12.02	A	HB53	HB48
Cordoba [6L2]	09.02 – 01.06	A	HB53	HB45
Cordoba [6L2]	02.06 – 11.09	B2	HB53	HB48
Cordoba Vario [6K5]	04.97 – 08.03	A	HB53	HB48
Ibiza [6K1]	03.93 – 05.02	A	HB53	HB48
Ibiza [6L1]	09.01 – 01.06	A	HB53	HB45
Ibiza [6L1]	02.06 – 11.09	B2	HB53	HB48
Ibiza [KJ1]	01.17 →	B2	HB65	HB40
Ibiza SC [6J1]	02.08 – 08.11	B2	HB60	HB40
Ibiza SC [6J1, 6P1]	09.11 – 05.17	B2	HB60	HB40
Ibiza ST [6J8]	03.10 – 08.11	B2	HB60	HB40
Ibiza ST [6J8, 6P8]	09.11 – 05.17	B2	HB60	HB40
Inca [6K9]	11.95 – 06.03	A	HB50	HB45
Leon [1M1]	10.98 – 06.06	A	HB53	HB48
Leon [1P1]	07.05 – 02.09	B1	HB65	HB65
Leon [1P1]	03.09 – 12.12	B1	HB65	HB65
Leon [5F1]	09.12 →	B2	HB65	HB40
Leon SC [5F5]	01.13 – 12.18	B2	HB65	HB40
Leon SC Cupra [5F5]	01.13 – 12.18	B2	HB65	HB40
Leon ST [5F8]	08.13 →	B2	HB65	HB40
Mii [KF1]	10.11 →	B2	HB60	HB40
Toledo [1M2]	10.98 – 07.04	A	HB53	HB45
Toledo [KG3]	07.12 →	B2	HB60	HB40

SKODA

Citigo	10.11 →	B2	HB60	HB40
Fabia [6Y2]	09.99 – 03.08	A	HB53	HB48
Fabia [5J2]	12.06 – 05.13	B2	HB53	HB53
Fabia [5J2]	06.13 – 12.14	B2	HB53	HB53
Fabia [NJ3]	08.14 →	B2	HB60	HB40
Fabia Combi [6Y5]	12.99 – 12.07	A	HB53	HB48
Fabia Combi [5J5]	12.06 – 05.13	B2	HB53	HB53
Fabia Combi [5J5]	06.13 – 12.14	B2	HB53	HB53
Fabia Combi [NJ5]	08.14 →	B2	HB60	HB40
Felicia [6U1]	10.94 – 08.01	A	HB50	HB50
Felicia Combi [6U5]	10.94 – 08.01	A	HB50	HB50
Karoq [NU7]	07.17 →	B2	HB65	HB45
Kodiahq [NS7]	02.17 →	B2	HB60	HB53
Octavia [1U2]	09.96 – 12.10.	A	HB53	HB48





SKODA

Octavia [1Z3]	05.04 – 06.13	C	HB60	HB48
Octavia [5E3]	11.12 →	B2	HB60	HB48
Octavia Combi [1U5]	10.96 – 12.10	A	HB53	HB48
Octavia Combi [1Z5]	05.04 – 06.13	C	HB60	HB48
Octavia Combi [5E5]	11.12 →	B2	HB60	HB48
Praktik [5J7]	03.07 – 05.15.	B2	HB53	HB53
Rapid [NH3]	07.12 →	B2	HB60	HB40
Rapid Spaceback [NH3]	10.13 →	B2	HB60	HB40
Roomster [5J7]	03.06 – 05.15	B2	HB53	HB53
Superb [3T4]	12.01 – 10.04	C	HB53	HB53
Superb [3U4]	11.04 – 03.08	A	HB53	HB50
Superb Combi [3T5]	03.08 – 05.15	B2	HB60	HB45
Superb Combi [3V5]	05.15 →	B2	HB65	HB45
Yeti [5L7]	05.09 – 12.17	B2	HB60	HB48

SMART (MCC)

Smart Cabrio [450]	03.00 – 01.04	A	HB53	HB53
Smart Coupé [450]	07.98 – 01.04	A	HB53	HB53
Forfour [454]	01.04 – 06.07	A	HB65	HB45
Fortwo Cabrio [450]	02.04 – 03.07	A	HB53	HB53
Fortwo Cabrio [451]	04.07 – 12.15	B1	HB58	HB53
Fortwo Coupé [450]	02.04 – 03.07	A	HB53	HB53
Fortwo Coupé [451]	04.07 →	B1	HB58	HB53
Roadster [452]	04.03 – 11.05	A	HB50	HB45
Roadster Coupé [452]	04.03 – 11.05	A	HB50	HB45

SSANGYONG

Actyon	10.05 →	A	HB53	HB48
Actyon Sports	03.07 →	A	HB53	HB48
Korando [KJ]	07.96 – 12.05	A	HB45	HB45
Korando C	02.11 →	A	HB60	HB40
Kyron	05.05 – 02.07	A	HB55	HB48
Kyron	03.07 →	A	HB55	HB48
Musso [MJ]	07.93 – 12.05	A	HB50	HB45
Rexton	09.01 – 12.10	A	HB50	HB50
Rexton II	10.08 – 12.12	A	HB50	HB50
RextonW	06.12 →	A	HB50	HB50
Rodius	08.04 – 12.12	A	HB60	HB45
Rodius II	05.13 →	A	HB60	HB40
Tivoli	07.15 →	A	HB60	HB40
XLV	04.16 →	A	HB60	HB40

SUBARU

BRZ [Z10]	01.12 →	A	HB55	HB50
Forester [SF]	01.97 – 05.02	A	HB53	HB48
Forester [SG]	06.02 – 05.03	A	HB53	HB48
Forester [SG]	06.03 – 11.07	A	HB53	HB48
Forester [S12]	12.07 – 12.12	A	HB60	HB45
Forester [S13]	11.12 →	A	HB65	HB40
Impreza [G12/G22]	06.07 – 12.11	A	HB60	HB40
Impreza [G13/G23]	10.11 – 08.16	A	HB65	HB40
Impreza Sedan [GC,GF]	01.93 – 09.00	A	HB53	HB45
Impreza Sedan [GD,GG]	10.00 – 06.07	A	HB55	HB40
Impreza Outback [GD,GG]	10.00 > 06.07	A	HB55	HB40
Impreza Kombi [GC,GF]	08.98 – 09.00	A	HB53	HB45
Impreza Kombi [GD,GG]	10.00 – 01.04	A	HB55	HB40
Impreza Kombi [GD,GG]	02.04 – 06.07	A	HB55	HB40
Impreza Sports Wagon	11.92 – 07.00	A	HB53	HB45
Justy [MS]	10.96 – 08.03	A	HB53	HB45
Justy [G3X]	09.03 – 08.07	A	HB48	HB40
Justy [M3]	09.07 – 12.10	A	HB50	HB40
Legacy [BL/BP]	07.03 – 05.09	A	HB60	HB45
Legacy [B14]	06.09 →	A	HB65	HB48
Legacy Outback [BE/BH]	10.98 – 06.03	A	HB55	HB50



SUBARU

Legacy Outback [BL/BP]	07.03 – 05.09	A	HB60	HB45
Legacy Kombi [BE/BH]	10.98 – 06.03	A	HB55	HB50
Legacy Kombi [BL/BP]	07.03 – 05.09	A	HB60	HB45
Legacy Kombi [B14]	06.09 – 12.14	A	HB65	HB48
Levorg [VM,V10]	06.14 →	A	HB65	HB40
Outback [B14]	06.09 →	A	HB65	HB48
Outback [B15]	03.15 →	A	HB65	HB40
Tribeca [W10]	11.07 – 01.14	A	HB65	HB50
WRX [V10]	05.14 →	A	HB65	HB40
XV [G33]	08.11 – 11.17	A	HB65	HB40

SUZUKI

Alto [EF]	10.94 – 02.02	A	HB48	HB45
Alto [MA]	02.02 – 12.06	A	HB45	HB40
Baleno	03.16 →	A	HB53	HB45
Baleno Sedan	04.95 – 09.05	A	HB50	HB45
Baleno Hatchback	04.95 – 09.05	A	HB50	HB45
Baleno Wagon	08.96 – 09.07	A	HB50	HB45
Carry [FD]	03.99 – 03.09	A	HB40	HB40
Grand Vitara	03.98 – 09.05	A	HB48	HB48
Grand Vitara [JT]	10.05 →	A	HB48	HB48
Ignis Hatchback	10.00 – 12.07	A	HB48	HB45
Ignis [MF]	10.16 →	A	HB53	HB48
Jimny [FJ]	10.98 →	A	HB45	HB40
Kizashi	10.09 →	A	HB60	HB50
Liana Hatchback	03.01 – 04.08	A	HB55	HB48
Splash [A5B]	01.08 →	A	HB55	HB40
Swift [Z]	11.14 →	A	HB53	HB45
Swift Hatchback [MA]	03.96 – 12.04	A	HB53	HB45
Swift Hatchback [MZ/EZ]	11.04 – 12.14	A	HB53	HB45
Swift Hatchback [AZH,AZG]	09.10 →	A	HB53	HB45
Swift Sedan [MA]	03.96 – 12.04	A	HB53	HB45
Swift Sedan [Z]	11.04 →	A	HB53	HB45
Swift Hatchback [A2L]	05.17 →	A	HB50	HB48
Vitara [ET]	01.95 – 12.05	A	HB45	HB45
Vitara [LY]	02.15 →	A	HB60	HB40
Wagon R+ [EM]	10.96 – 05.00	A	HB50	HB45
Wagon R+ [MM]	05.00 – 08.08	A	HB50	HB45
X-90	09.95 – 08.98	A	HB50	HB45

TOYOTA

Auris [E15,JTN]	10.06 – 08.12	A	HB65	HB40
Auris [E15,NMT,SB1]	02.07 – 10.12	A	HB65	HB40
Avensis [T22]	10.97 – 01.03	A	HB53	HB45
Avensis [T25]	01.03 – 11.08	A	HB60	HB40
Avensis Verso [M2]	05.01 – 11.09	A	HB65	HB40
Avensis Wagon [T22]	10.97 – 01.03	A	HB53	HB45
Avensis Wagon [T25]	01.03 – 11.08	A	HB60	HB40
Aygo	02.05 – 12.14	A	HB65	-
Aygo [B4]	05.14 →	B1	HB65	-
Camry [V2]	06.96 – 08.01	A	HB53	HB45
Camry [V3]	08.99 – 01.06	A	HB53	HB45
Camry [V3]	08.01 – 01.06	A	HB65	HB45
Camry [V4,V40]	01.06 →	A	HB60	HB50
Camry [V5]	08.11 →	A	HB65	HB45
Camry [V7]	04.18 →	A	HB65	HB50





TOYOTA

Celica Cabrio [T20]	08.94 – 05.99	A	HB53	HB48
Celica Coupé [T23]	08.99 – 09.05	A	HB65	HB40
Celica Liftback [T20]	11.93 – 08.99	A	HB53	HB48
Corolla [E11]	05.95 – 08.02	A	HB50	HB45
Corolla [E12]	08.00 – 08.08	A	HB55	HB48
Corolla [E12]	10.02 – 08.08	A	HB60	HB40
Corolla Hatchback [E11]	05.97 – 07.01	A	HB50	HB45
Corolla Hatchback [E12]	11.01 – 11.06	A	HB60	HB40
Corolla Hatchback [E12,SB1]	11.01 – 12.07	A	HB55	HB48
Corolla Liftback [E11]	05.97 – 11.01	A	HB50	HB45
Corolla Verso [E12]	09.01 – 01.04	A	HB65	HB40
Corolla Verso [R1]	02.04 – 02.09	A	HB65	HB40
Corolla Wagon [E11]	04.97 – 09.01	A	HB50	HB45
Corolla Wagon [E12]	08.00 – 02.07	A	HB60	HB40
GT86	04.12 →	A	HB55	HB50
Hilux [Raider]	05.05 →	A	HB53	HB48
Hilux [N15,N25,N26,N35]	07.05 →	A	HB53	HB48
Hilux [N12,N13]	06.15 →	A	HB55	HB40
Hilux Pickup [N8...19]	08.88 – 08.05	A	HB40	HB40
iQ	11.08 - -05.14	A	HB53	HB45
Land Cruiser [J9]	04.96 – 12.06	A	HB48	HB45
Land Cruiser [J10]	01.98 – 07.08	A	HB60	HB55
Land Cruiser [J12]	09.02 – 08.09	A	HB55	HB53
Land Cruiser [J20]	09.07 →	A	HB60	HB55
Land Cruiser [J15]	08.09 →	A	HB65	HB50
Land Cruiser Prado [J9]	04.96 – 09.04	A	HB48	HB45
Land Cruiser Prado [J15]	09.09 →	A	HB65	HB50
MR2 Cabrio [W3]	12.99 – 05.06	A	HB50	HB48
Paseo [L5]	08.95 – 08.99	A	HB50	HB45
Picnic	09.96 – 05.01	A	HB60	HB40
Previa	02.00 – 01.06	A	HB70	HB45
Prius [W20]	09.03 – 03.09	A	HB65	HB40
Prius [W30,W35]	04.09 →	A	HB65	HB40
Prius + [W40]	03.12 →	A	HB65	HB38
Proace [G9]	06.13 – 01.16	A	HB70	HB50
RAV4 [A1]	04.94 – 08.00	A	HB50	HB45
RAV4 [A2]	05.00 – 01.06	A	HB60	HB48
RAV4 [A3]	11.05 – 11.12	A	HB60	HB40
RAV4 [A4]	12.12 →	A	HB65	HB40
RAV4 Cabrio [A1]	11.95 – 08.00	A	HB50	HB45
Verso [R2]	02.09 →	A	HB65	HB40
Yaris [P1]	01.99 – 08.05	A	HB53	HB38
Yaris (F) [P1]	01.01 – 08.06	A	HB53	HB38
Yaris Verso [P2]	08.99 – 11.02	A	HB55	HB40
Yaris Verso [P2]	12.02 – 09.05	A	HB55	HB40

VOLVO

C30	10.06 →	B2	HB65	HB50
C70 Coupé	01.97 – 07.02	A	HB53	HB53
C70 I Cabrio	02.98 – 03.06	A	HB53	HB53
C70 II Cabrio	03.06 – 12.13	B2	HB65	HB48
S40 I	09.95 – 01.04	A	HB50	HB50
S40 II [P11]	12.03 – 08.05	C	HB65	HB50
S40 II [P11]	08.05 – 12.12	B2	HB65	HB50
S60 Cross Country	08.15 →	B2	HB65	HB50
S60 I	11.00 – 07.04	A	HB60	HB53
S60 I	08.04 – 07.09	B1	HB60	HB53
S60 II	11.10 →	B2	HB65	HB50
S70	01.97 – 07.00	A	HB53	HB53
S80 I	08.04 – 07.06	B1	HB60	HB53
S80 II	03.06 – 12.16	B2	HB65	HB50
S90 II	03.16 →	B2	HB60	HB50
V40 Cross Country	01.13 →	B2	HB65	HB48
V40 I	01.95 – 04.00	A	HB50	HB50
V40 I	05.00 – 08.04	A	HB50	HB50
V40 II	09.12 →	B2	HB65	HB48
V50	04.04 – 07.05	C	HB65	HB50



VOLVO

V50	08.05 – 12.12	B2	HB65	HB50
V60 Cross Country	08.15 →	B2	HB65	HB50
V60 I	09.10 – 06.15	B2	HB65	HB50
V60 I	06.15 →	B2	HB65	HB50
V70 I	01.97 – 03.00	A	HB53	HB53
V70 II	03.00 – 07.03	A	HB60	HB53
V70 II	08.03 – 07.04	A	HB60	HB53
V70 II	08.04 – 07.07	B1	HB60	HB53
V70 III	08.07 →	B2	HB65	HB50
V90 Cross Country	02.17 →	B2	HB60	HB50
V90 II	03.16 →	B2	HB60	HB50
XC40	12.17 →	B2	HB60	HB50
XC60	03.09 – 07.10	B2	HB65	HB50
XC60	08.10 – 07.17	B2	HB65	HB50
XC70 I	08.02 – 07.03	A	HB60	HB53
XC70 I	08.03 – 07.04	A	HB60	HB53
XC70 I	08.04 – 07.07	B1	HB60	HB53
XC70 II	08.07 →	B2	HB65	HB50
XC90 I	10.02 – 07.04	A	HB60	HB53
XC90 I	08.04 – 07.10	B1	HB60	HB53
XC90 I	08.10 – 07.16	B1	HB60	HB53
XC90 II	06.15 →	B2	HB60	HB50

VW (VOLKSWAGEN)

Amarok [2H]	09.10 – 04.12	A	HB60	HB58
Amarok [2H]	05.12 – 10.16	B2	HB60	HB60
Amarok [S6,S7]	06.16 →	B2	HB60	HB60
Arteon [3H7]	03.17 →	B2	HB65	HB48
Beetle [5C1,5C2]	04.11 →	B2	HB53	HB53
Beetle Cabriolet [5C7,5C8]	01.13 →	B2	HB53	HB53
Bora [1J2]	09.98 – 05.02	A	HB53	HB48
Bora [1J2]	06.02 – 05.05	C	HB53	HB45
Bora Variant [1J6]	09.98 – 05.02	A	HB53	HB48
Bora Variant [1J6]	06.02 – 05.05	C	HB53	HB45
Caddy [9K9]	11.95 – 06.03	A	HB53	HB45
Caddy [2K]	02.04 – 10.06	C	HB60	HB45
Caddy [2K]	11.06 – 08.10	B2	HB60	HB45
Caddy [2C]	09.10 – 05.15	B2	HB60	HB45
Caddy [SA]	05.15 – 05.17	B2	HB60	HB45
Caddy [SA]	06.17 →	B2	HB60	HB45
Caddy Pickup [9U7]	06.96 – 12.00	A	HB53	HB45
California T4 [70,7D]	09.90 – 06.03	A	HB53	HB53
California T5 [7E]	06.13 – 08.15	B2	HB60	HB60
California T6 [SG]	04.15 →	B2	HB60	HB60
Caravelle T4 [70,7D]	09.90 – 06.03	A	HB53	HB53
Caravelle T5 [7E]	06.13 – 08.15	B2	HB60	HB60
Caravelle T6 [SG]	04.15 →	B2	HB60	HB60
CC [358]	11.11 – 12.16	B2	HB60	HB48
Crafter [2E]	04.06 – 12.16	B1	HB65	HB60
Crafter [SY,SZ]	09.16 →	B2	HB70	HB65
Eos [1F7,1F8]	05.06 – 08.15	B2	HB60	HB48
Fox [5Z1]	04.05 – 12.12	A	HB53	HB38
Golf III [1H1]	11.91 – 12.97	A	HB53	HB48
Golf III Cabriolet [1E7]	09.93 – 04.98	A	HB53	HB48
Golf III Variant [1H5]	07.93 – 02.99	A	HB53	HB48
Golf IV [1J1]	10.97 – 05.02	A	HB53	HB48
Golf IV [1J1]	06.02 – 06.05	C	HB53	HB45
Golf IV Cabriolet [1E7]	04.98 – 06.02	A	HB53	HB48
Golf IV Variant [1J5]	05.99 – 05.02	A	HB53	HB48





VW (VOLKSWAGEN)

Golf IV Variant [1J5]	06.02 – 06.06	C	HB53	HB45
Golf V [1K1]	10.03 – 10.05	C	HB60	HB48
Golf V [1K1]	11.05 – 11.08	B2	HB60	HB48
Golf V Variant [1K5]	05.07 – 07.09	B2	HB60	HB48
Golf VI [5K1]	10.08 – 11.12	B2	HB60	HB48
Golf VI Cabriolet [517]	03.11 – 05.16	B2	HB60	HB48
Golf VI Variant [AJ5]	06.09 – 04.13	B2	HB60	HB48
Golf VII [5G1, BQ1]	08.12 →	B2	HB65	HB45
Golf VII Variant [BA5, BV5]	04.13 →	B2	HB65	HB45
Golf Sportsvan [AM1]	02.14 →	B2	HB70	HB40
Jetta [1K2]	01.05 – 11.05	C	HB60	HB48
Jetta [1K2]	12.05 – 10.10	B2	HB60	HB48
Jetta [162,163,AV2]	02.11 →	B2	HB60	HB48
LT [2D,2H]	05.96 – 04.06	A	HB60	HB53
Lupo [6X1]	06.98 – 05.03	A	HB53	HB48
Lupo [6X1]	06.03 – 07.05	C	HB48	HB45
Multivan T4 [70,7D]	09.90 – 06.03	A	HB53	HB53
Multivan T5 [7H, 7E]	02.03 – 05.13	A	HB60	HB60
Multivan T5 [7E]	06.13 – 08.15	B2	HB60	HB60
Multivan T6 [SG]	04.15 →	B2	HB60	HB60
Passat [3B3]	11.01 – 05.05	C	HB55	HB48
Passat [3C2]	03.05 – 11.10	B2	HB60	HB48
Passat [362]	08.10 – 05.12	B2	HB60	HB48
Passat [362]	08.11 – 12.14	B2	HB60	HB48
Passat [3G2]	08.14 →	B2	HB65	HB48
Passat Alltrack [365]	01.12 – 12.14	B2	HB60	HB48
Passat Alltrack [3G5]	05.15 →	B2	HB65	HB48
Passat CC [357]	05.08 – 11.11	B2	HB60	HB48
Passat CC [357]	12.11 – 05.12	B2	HB60	HB48
Passat Variant [3B6]	11.01 – 05.05	C	HB55	HB48
Passat Variant [3C5]	08.05 – 11.10	B2	HB60	HB48
Passat Variant [365]	08.10 – 05.12	B2	HB60	HB48
Passat Variant [365]	08.11 – 12.14	B2	HB60	HB48
Passat Variant [3G5]	08.14 →	B2	HB65	HB48
Polo [6N2]	07.98 – 09.01	A	HB48	HB48
Polo [9N3]	05.05 – 12.09	B2	HB53	HB48
Polo [6R1,6C1]	06.09 →	B2	HB60	HB40
Polo [AW1]	06.17 →	B2	HB65	HB45
Polo Classic [6V2]	11.95 – 09.01	A	HB53	HB45
Polo Classic [9N4]	04.05 – 02.10	B2	HB53	HB48
Polo Variant [6V5]	05.97 – 09.01	A	HB53	HB45
Scirocco [137,138]	08.08 – 11.17	B2	HB60	HB48
Sharan [7N1,7N2]	05.10 →	B2	HB70	HB40
Tiguan [5N1,5N2]	11.07 – 08.17	B2	HB60	HB53
Tiguan [AD1; BT1]	01.16 →	B2	HB65	HB55
Tiguan Allspace [BW2]	03.17 →	B2	HB65	HB55
Touareg [7LA;7L6]	11.02 – 05.10	C	HB65	HB65
Touareg [7P5]	01.10 – 12.14	C	HB65	HB65
Touran [1T1]	02.03 – 11.06	C	HB60	HB45
Touran [1T2]	11.06 – 05.10	B2	HB60	HB45
Touran [1T3]	05.10 – 05.15	B2	HB60	HB45
Touran [5T1]	05.15 →	B2	HB70	HB40
Transporter T4 [70,7D]	09.90 – 06.03	A	HB53	HB53
Transporter T5 [7E, 7F]	02.03 – 05.13	A	HB60	HB58
Transporter T5 [7E, 7F, 7H, 7J]	06.13 – 08.15	B2	HB60	HB60
Transporter T6 [SF,SG]	04.15 →	B2	HB60	HB60
T-Roc	07.17 →	B2	HB65	HB50
up! [121,122]	12.11 →	B2	HB60	HB40
Vento [1H2]	11.91 – 12.97	A	HB53	HB48





MTS MarkenTechnikService GmbH & Co. KG
Carl-Benz-Straße 2
76761 Rülzheim – Germany
www.mts-gruppe.com

Intertec Polska Sp. z o.o.
Stara Wies, ul. Grodziska 22
05-830 Nadarzyn – Poland
www.intertec-polska.pl

Tegro AG • Ringstr. 3
3603 Schwerzenbach – Switzerland
www.tegro.ch

Art.-Nr.: 95347 Stand: 03/2021

